



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

Report Date: September 20, 2006

Supervisor DRH

Mine Name: Tetla Septarian Mine  
Operator Name: West Desert Collectors  
Robert or Shawn Harris  
278 West Main  
P.O. Box 102  
Delta, Utah 84624

Permit number: S/025/006  
Date: September 11, 2006  
Time: 5:00 PM

Inspector(s): Doug Jensen  
Other Participants: None  
Mine Status: Inactive

Weather: Clear, warm

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Water Impoundments	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Air Quality	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:  
Inspected the site while in the area.

Directions to Site:  
See previous inspection memo

Inspection Summary:  
6. Concurrent Reclamation  
The hole created by mining has been recontoured and apparently seeded. There are marks left by a harrow that had been drug over the recontoured area. The Division did not witness the seeding so it is unknown how the seeding was done. There was no evidence of any vegetation success on the areas recently seeded. Much of the site reclaimed previously is covered with Russian thistle.  
The trackhoe that had been located on the site for several years has been removed.

Conclusions and Recommendations:  
I will continue to monitor the site to assess the vegetation success.

Inspector's Signature Doug Jensen Date: 9/20/06

S/025/0006  
Page 2 of 2

**Inspection Date:** September 20, 2006 ; **Report Date:** July 20, 2006

dj:pb

cc: Robert Harris  
Will Stokes, SITLA, ML-48588

O:\M025-Kane\S0250006-TetlaSeptarian\inspections\09112006insp.doc



